

Unclassified

Description  
New flooring in Corridor  
226

Taken Date  
07/21/2023 at 03:26 pm

Upload Date  
07/21/2023 at 04:33 pm

Uploaded By  
India Williams

File Name  
[0A0A30BA-E2D9-4017-9...](#)



Unclassified

Description  
Floor prep in Classroom 6  
(Rm 324)

Taken Date  
07/21/2023 at 07:50 am

Upload Date  
07/21/2023 at 07:54 am

Uploaded By  
India Williams

File Name  
[4F0BAF4C-0096-4943-B...](#)



Unclassified

Description  
New ceiling mold flange in  
Corridor 320

Taken Date  
07/21/2023 at 07:49 am

Upload Date  
07/21/2023 at 07:54 am

Uploaded By  
India Williams

File Name  
[2970E7C3-8F65-4822-B...](#)



Unclassified

Description  
Millwork installed in  
Teacher (Rm 231)

Taken Date  
07/21/2023 at 07:46 am

Upload Date  
07/21/2023 at 07:58 am

Uploaded By  
India Williams

File Name  
[DA0934FE-6C5A-4CEC-9...](#)



Unclassified

Description  
Painted frames to Tutoring  
(Rm 224) and Copy/  
Storage (Rm 222)

Taken Date  
07/21/2023 at 07:45 am

Upload Date  
07/21/2023 at 07:56 am

Uploaded By  
India Williams

File Name  
[33FFECD8-8853-4D41-B...](#)



Unclassified

Description  
New paint in Corridor 226

Taken Date  
07/21/2023 at 07:45 am

Upload Date  
07/21/2023 at 07:54 am

Uploaded By  
India Williams

File Name  
[CCCFE012-724D-41A0-8...](#)

